



The MATRIX-System

Form Adapting Support Technique

X-Support SXS



Versatile

Arrange the work piece, fix the pins in seconds you have a part-specific fixture.

Small pins for large work pieces.

X-Support SXS is flexible and applicable. 37 pins (\varnothing 2.5 mm) provide a surface of 26 mm² for a safe hold.

Use

For large and complicated work pieces on portal and horizontal arm measurement machines (HAM).

Contour-exact casting, for example when analyzing parts in the automobile and engineering industry.

Abbildung: X-Support SXS with glass plate

